IL2.35NKA

XJ



IL2.35LKA

XJ



IL2.35NKA

XK



XK



XF Sportbrake



XF Sportbrake



XJ LWB



kann nicht aufgenommen werden
can not lifted up

XJ LWB



kann nicht aufgenommen werden
can not lifted up

XKR-S



XKR-S



F-Type



kann nicht aufgenommen werden
can not lifted up

F-Type



kann nicht aufgenommen werden
can not lifted up

XF Saloon



kann nicht aufgenommen werden
can not lifted up

XF Saloon



kann nicht aufgenommen werden
can not lifted up

Abgebildete Punkte sind die vom
Hersteller freigegebenen Aufnahmepunkte.
The points are showing the prescribed points from the
vehicle manufacturer.

Maß- und Konstruktionsänderungen vorbehalten!
subject to alterations!

REV	CO NUM	DATE	BY

UNLESS OTHERWISE NOTED:
ANGULAR DIMENSIONS: +/-1 °
OTHER DIMENSIONS: +/- 0.8mm (<305mm)
+/- 1.6mm (>or= 305mm)

THIRD ANGLE PROJECTION

DO NOT SCALE DRAWING

UNLESS OTHERWISE SPECIFIED:
0.8mm MIN. CORNER BREAK
REMOVE ALL BURRS

NOTES:

The design and detail illustrated in this drawing is the property of Rotary Lift. It is being loaned with the expressed condition that it will not be duplicated or used except by permission and is subject to return upon request.

XS30CAT
with JAGUAR

ROTARY LIFT
A DOVER COMPANY

DRAWN: MiGo
DATE: 29.11.2017
SHEET
APPROVED: -
DRAWING NUMBER: Scissor-Lift_XS30CAT_8812